

2/22/09



Figure 1: Lack of an effective combination of erosion and sediment control BMPs



Figure 2: Lack of an effective combination of erosion and sediment control BMPs



Figure 3: Storm water from the site flowing in a channel adjacent to highway 88 right-of-way



Figure 4: Turbid storm water discharging into the eastern culvert



Figure 5: Another view of turbid storm water discharging into the eastern culvert which flows into Jackson Creek



Figure 6: Looking at the western discharge location in the distance

2/22/09



Figure 7: Storm water in the Caltrans right-of-way flowing to the western discharge location



Figure 8: Turbid storm water flowing down to the western discharge location



Figure 9: Lack of an effective combination of erosion and sediment control BMPs on the slope adjacent to Highway 88



Figure 10: Lack of effective BMPs upslope of the western discharge location Note: the large rill that is forming at the top of the slope



Figure 11: Lack of effective BMPs on top of the slope above the western discharge location



Figure 12: Area where concrete drain along the slope discharges into the area that flows down to the western discharge location Note: the lack of BMPs other than rip-rap

2/22/09



Figure 13: Lack of an effective combination of erosion and sediment control BMPs



Figure 14: Lack of an effective combination of erosion and sediment control BMPs



Figure 15: Lack of an effective combination of erosion and sediment control BMPs



Figure 16: Lack of an effective combination of erosion and sediment control BMPs Note: the poorly stabilized stockpile



Figure 17: Turbid storm water in the concrete channel that runs along the slope on the northern side of the project



Figure 18: Lack of an effective combination of erosion and sediment control BMPs

2/22/09



Figure 19: Lack of an effective combination of erosion and sediment control BMPs



Figure 20: Lack of an effective combination of erosion and sediment control BMPs



Figure 21: Lack of an effective combination of erosion and sediment control BMPs Note: the turbid storm water ponded adjacent to one of the discharge locations



Figure 22: Turbid storm water flowing on the site Note: the lack of effective storm water management BMPs



Figure 23: Turbid storm water ponded onsite just prior to discharge into the eastern culvert



Figure 24: Lack of an effective combination of erosion and sediment control BMPs

2/22/09



Figure 25: Lack of an effective combination of erosion and sediment control BMPs Note: the only BMPs observed were a few small fiber rolls



Figure 26: Lack of an effective combination of erosion and sediment control BMPs around one of the discharge locations



Figure 27: Lack of an effective combination of erosion and sediment control BMPs



Figure 28: Lack of an effective combination of erosion and sediment control BMPs



Figure 29: Lack of an effective combination of erosion and sediment control BMPs



Figure 30: Lack of an effective combination of erosion and sediment control BMPs



Figure 31: Lack of an effective combination of erosion and sediment control BMPs



Figure 32: Lack of an effective combination of erosion and sediment control BMPs



Figure 33: Turbid storm water discharging from the project



Figure 34: Turbid storm water from the site flowing into Jackson Creek



Figure 35: Turbid storm water from the site mixing with clean storm water in Jackson Creek



Figure 36: Turbid storm water from the site mixing with clean storm water in Jackson Creek